

Maintenance Manager
Maintenance Department

Dear Sir/Madam

Reduced Pressure Zone Valve Mandatory Testing

Our records show you have one or more BA Type Backflow prevention device - commonly known as an RPZ Valve assembly installed on your premises.

In accordance with the Water Regulations and Information and Guidance Note (IGN) 9-03-02, RPZ Valves must be tested by an **Accredited Tester** at least once a year to ensure the device is operating correctly. This can be carried out up to one month before the expiry date is due. Details are available on the Water Regulations Advisory Scheme web site - www.wras.co.uk

Arrow Valves have regional Accredited Testers who have been trained to service Caleffi and Brandoni RPZ Valves. Our Testers also carry Caleffi and Brandoni spares and should your valve fail the test, they will replace the individual part concerned with a genuine Caleffi or Brandoni unit. To minimise costs, we do not replace all the internal parts unless the client specifically instructs the Tester to do so.

Please contact us if the RPZ Valve is uninstalled, moved to a new location or you would like a quotation for testing.

Kind Regards
Sales Department